

THE UNITED REPUBLIC OF TANZANIA

## MINISTRY OF INDUSTRY AND TRADE

TANZANIA BUREAU OF STANDARDS (TBS)



Member of the International Standardization (ISO), Codex Alimentarius Commission (WHO/FAO), Agent for ISO and other National Standards Bodies

In reply please quote: Ref. No.: TBS/MEDC/A-3/38

Date: 2024 - 04 - 23

All Interested Stakeholders All Relevant Ministries/Institutions/Organizations/Companies

Dear Sir/Madam,

## **RE: DRAFT TANZANIA STANDARDS FOR STAKEHOLDERS' COMMENTS**

Please refer to the heading above.

- 2. Tanzania Bureau of Standards (TBS) is in the process of developing standards on:
  - a) MEDC 3 (2684) DTZS/ ISO 13623:2017- Petroleum and natural gas industries Pipeline transportation systems.
  - b) MEDC 3 (2685) DTZS/ ISO 15590-1:2018- Petroleum and natural gas industries Induction bends, fittings and flanges for pipeline transportation systems Part 1: Induction bends.
  - c) MEDC 3 (2686) DTZS/ ISO 15590-2:2021 Petroleum and natural gas industries Factory bends, fittings and flanges for pipeline transportation systems Part 2: Fittings.
  - d) MEDC 3 (2687) DTZS/ ISO 15590-3:2022 Petroleum and natural gas industries. Factory bends, fittings and flanges for pipeline transportation systems Part 3: Flanges.
  - e) MEDC 3 (2688) DTZS/ ISO 15590-4:2019 Petroleum and natural gas industries Factory bends, fittings and flanges for pipeline transportation systems Part 4: Factory cold bends.
  - MEDC 3 (2689) DTZS/ ISO 3183:2019 Petroleum and natural gas industries Steel pipe for f) pipeline transportation system (Revision: TZS 2255: 2018 - ISO 3183: 2012).
  - g) MEDC 3 (2690) DTZS/ ISO 16924:2016 Natural gas fuelling stations LNG stations for fuelling vehicles.
  - h) MEDC 3 (2691) DTZS/ ISO 15995:2021- Gas Cylinders Specifications and testing of LPG cylinder valves - manually operated.
  - MEDC 11 (2737) DTZS/ ISO 16330:2003- Reciprocating positive displacement pumps and i) pump units -Technical requirements
  - MEDC 11 (2721) DTZS/ ISO 17089-1:2019 Measurement of fluid flow in closed conduits j) Ultrasonic meters for gas Part 1: Meters for custody transfer and allocation measurement.

TBS HEADQUARTERS Physical Address Tanzania Bureau of Standards Ubungo, Morogoro Road / Sam Nujoma Road P. O. Box 9524 DAR ES SALAAM, TANZANIA Tel. No: +255 22 245 0298/ +255 22 245 0206 Telefax: +255 22 2450959 Hotline: 0800110827 E-mail: info@tbs.go.tz Website: http://www.tbs.go.tz E-mail address for customer complaints: complaints@tbs.go.tz Twitter: TBS\_Tanzania Instagram: tbs\_Viwango

TBS CENTRAL ZONE Physical Address Kambarage Tower P.O. Box 2956 DODOMA, TANZANIA Tel. No +255 26 2520310

TBS LAKE ZONE Physical Address NSSF Building, 3rd Floor P.O. Box 1814 MWANZA TANZANIA Tel. No:

TBS NORTHERN ZONE Physical Address NSSF Mafao House Building, 2<sup>nd</sup> Floor P.O. Box 2399 ARUSHA TANZANIA Tel. No: +255 28 2501127 +255 27 2520143

TBS SOUTHERN HIGHLANDS ZONE Physical Address NHIF Building, 7<sup>th</sup> Floor P.O. Box 1674 MBEYA TANZANIA Tel No: +255 25 2502848

**TBS SOUTHERN ZONE** Physical Address MTUWASA Building P. O. Box 1396 MTWARA TANZANIA Tel. No +255 23 2334477

**TBS WESTERN ZONE** Physical Address NSSF Building (Mafao House), 2<sup>nd</sup> Floor . O. Box 1276 KIGOMA TANZANIA Tel. No: +255 28 2804023

- k) MEDC 11 (2094) DTZS/ ISO 5167-5:2022 Measurement of fluid flow by means of pressure differential devices inserted in circular cross-section conduits running full - Part 5: Cone meter.
- I) MEDC 9 (2705) DTZS/ISO 20826:2006 Automotive LPG components Containers
- m) MEDC 9 (2706) DTZS/ ISO 8789:2020 Rubber hoses and hose assemblies for liquefied petroleum gas in motor vehicles Specification.
- n) MEDC 9 (2707) DTZS/ ISO 20766-1:2018 Road vehicles Liquefied petroleum gas (LPG) fuel systems components Part 1: General requirements and definitions.
- MEDC 9 (2708) DTZS/ ISO 20766-2:2018 Road vehicles Liquefied petroleum gas (LPG) fuel systems components - Part 2: Performance and general test methods.
- p) MEDC 9 (2709) DTZS / ISO 20766-4:2018 Road vehicles Liquefied petroleum gas (LPG) fuel system components - Part 4: Level indicator.
- q) MEDC 9 (2710) DTZS/ ISO 20766-6:2018 Road vehicles Liquefied petroleum gas (LPG) fuel systems components Part 6: Pressure relief valves (PRV).
- r) MEDC 9 (2711) DTZS/ ISO 20766-8:2023 Road vehicles Liquefied petroleum gas (LPG) fuel system components Part 8: Fuel pump.
- s) MEDC 9 (2712) DTZS/ ISO 20766-14:2022 Road vehicles Liquefied petroleum gas (LPG) fuel system components Part 14: Vaporizer/pressure regulator.
- t) MEDC 9 (2713) DTZS/ ISO 20766-16:2022 Road vehicles Liquefied petroleum gas (LPG) fuel system components Part 16: Injectors and gas mixing device/fuel rail.
- u) MEDC 9 (2714) DTZS/ ISO 20766-25:2022 Road vehicles Liquefied petroleum gas (LPG) fuel system components Part 25: Gas connections.
- v) MEDC 2 (2364) DTZS, Standard practice for installation of double-twisted wire mesh gabions and revet mattresses
- w) MEDC 2 (2680) DTZS/ ISO 5951:2013 Hot-rolled steel sheet of higher yield strength with improved formability
- x) MEDC 2 (2681) DTZS/ ISO 16160:2012 Hot-rolled steel sheet products —Dimensional and shape tolerances
- y) MEDC 2 (2682) DTZS/ ISO 6929:2013 Steel products Vocabulary
- z) MEDC 2 (2683) DTZS/ ISO 5952:2019 Steel sheet, hot-rolled, of structural quality with improved atmospheric corrosion resistance
- aa) MEDC 2 (2735) DTZS/ ISO 630-5:2023 Structural steels Part 5: Technical delivery conditions for structural steels with improved atmospheric corrosion resistance
- bb) MEDC 2 (2736) DTZS/ ISO 630-6:2023 Structural steels Part 6: Technical delivery conditions for seismic-proof improved structural steels for building.
- cc) MEDC 1 (2692) DTZS/ ISO 16419:2013 Cork Visual anomalies of cork stoppers for still wines
- dd) MEDC 1 (2693) DTZS/ ISO 4710:2000 Cork Cylindrical stoppers for sparkling wines and gasified wines Characteristics
- ee) MEDC 1 (2386) DTZS/ ISO 9994:2018, Lighters Safety specifications
- ff) MEDC 1 (2387) DTZS/ ISO 22702:2018, Utility lighters Safety specifications
- gg) MEDC 1 (2694) DTZS/ ISO 10333-1:2000, Personal fall-arrest systems Part 1: Full-body harnesses
- hh) MEDC 1 (2695) DTZS/ ISO 10333-2:2000, Personal fall-arrest systems Part 2: Lanyards and energy absorbers
- ii) MEDC 1 (2696) DTZS/ ISO 10333-3:2000, Personal fall-arrest systems Part 3: Self-retracting lifelines

TBS HEADQUARTERS Physical Address Tanzania Bureau of Standards Ubungo, Morogoro Road / Sam Nujoma Road P. O. Box 9524 DAR ES SALAAM, TANZANIA Tel. No: +255 22 245 0298/ +255 22 245 0206 Telefax: +255 22 2450959 Hotline: 0800110827 E-mail: info@tbs.op.tz	TBS CENTRAL ZONE Physical Address Kambarage Tower P.O. Box 2956 DODOMA, TANZANIA Tel. No: +255 26 2520310	TBS LAKE ZONE Physical Address NSSF Building, 3 <sup>rd</sup> Floor P.O. Box 1814 MWANZA, TANZANIA Tel. No: +255 28 2501127	TBS NORTHERN ZONE Physical Address NSSF Mafao House Building, 2 <sup>nd</sup> Floor P.O. Box 2399 ARUSHA, TANZANIA Tel. No: +255 27 2520143	TBS SOUTHERN HIGHLANDS ZONE Physical Address NHIF Building, 7 <sup>th</sup> Floor P.O. Box 1674 MBEYA, TANZANIA Tel No: +255 25 2502848	TBS SOUTHERN ZONE Physical Address MTUWASA Building P. O. Box 1396 MTWARA, TANZANIA Tel. No: +255 23 2334477	TBS WESTERN ZONE Physical Address NSSF Building (Mafao House), 2 <sup>nd</sup> Floor P. O. Box 1276 KIGOMA, TANZANIA Tel. No: +255 28 2804023	

Website: http://www.tbs.go.tz E-mail address for customer complaints:

complaints@tbs.go.tz Twitter: TBS\_Tanzania Instagram: tbs\_Viwango

- jj) MEDC 1 (2697) DTZS/ ISO 10333-4:2002, Personal fall-arrest systems Part 4: Vertical rails and vertical lifelines incorporating a sliding-type fall arrester.
- kk) MEDC 1 (2698) DTZS/ ISO 10333-5:2001, Personal fall-arrest systems Part 5: Connectors with self-closing and self-locking gates
- II) MEDC 1 (2699) DTZS/ ISO 10333-6:2004, Personal fall-arrest systems Part 6: System performance tests
- mm) MEDC 1 (2700) DTZS/ ISO 14567:1999, Personal protective equipment for protection against falls from a height Single-point anchor devices
- nn) MEDC 1 (2701) DTZS/ ISO 16024:2005, Personal protective equipment for protection against falls from a height Flexible horizontal lifeline systems
- 3. According to procedures for preparation of Tanzania Standards, the draft standards are hereby being circulated for stakeholders' comments. Due to copyright issues, for International Standards only scope is provided, for fully standard visit TBS library.
- 4. Being one of the key stakeholders in standard development, we kindly request you to go through the draft standards (complete document for adopted ISO/IEC standards can be obtained from TBS library) and send your comments regarding its technical content. Suggestion which entails revision of text should indicate the preferred wording and the relevant clause should be quoted against each comment. In case you find it suitable and no comments, please notify accordingly.
- 5. Your comments can be submitted in electronic form or hard copy as per attached form.
- 6. We will appreciate receiving your comments before 22th June, 2024.
- 7. We thank you for your kindly and continued cooperation.
- 8. Sincerely yours,

Mohamedi Kaila

For: DIRECTOR GENERAL

TBS HEADQUARTERS

Physical Address Tanzania Bureau of Standards Ubungo, Morogoro Road / Sam Nujoma Road P. O. Box 9524 DAR ES SALAAM, TANZANIA Tel. No: +255 22 245 0298/ +255 22 245 0206 Telefax: +255 22 2450959 Hotline: 0800110827 E-mail: info@tbs.go.tz Website: http://www.tbs.go.tz E-mail address for customer complaints: complaints@tbs.go.tz Twitter: TBS\_Tanzania Instagram: tbs\_Viwango

TBS CENTRAL ZONE Physical Address Kambarage Tower P.O. Box 2956 DODOMA, TANZANIA Tel. No: +255 26 2520310

NE TBS LAKE ZONE Physical Address NSSF Building, 3<sup>rd</sup> Floor P.O. Box 1814 MWANZA, TANZANIA Tel. No: +255 28 2501127

TBS NORTHERN ZONE Physical Address NSSF Mafao House Building, 2<sup>nd</sup> Floor P.O. Box 2399 ARUSHA, TANZANIA Tel. No: +255 27 2520143 TBS SOUTHERN HIGHLANDS ZONE Physical Address NHIF Building, 7<sup>th</sup> Floor P.O. Box 1674 MBEYA, TANZANIA Tel No: +255 25 2502848 TBS SOUTHERN ZONE Physical Address MTUWASA Building P. O. Box 1396 MTWARA, TANZANIA TANZANIA Tel. No: +255 23 2334477 
 TBS WESTERN ZONE

 Physical Address

 NSSF Building (Mafao

 House), 2<sup>nd</sup> Floor

 P. O. Box 1276

 KIGOMA,

 TANZANIA

 Tel. No:

 +255 28 2804023



TBS HEADQUARTERS

Physical Address Tanzania Bureau of Standards Ubungo, Morogoro Road / Sam Nujoma Road P. O. Box 9524 DAR ES SALAAM, TANZANIA Tel. No: +255 22 245 0298/ +255 22 245 0206 Telefax: +255 22 2450959 Hotline: 0800110827 E-mail: info@tbs.go.tz Website: http://www.tbs.go.tz E-mail address for customer complaints: complaints@tbs.go.tz Twitter: TBS\_Tanzania Instagram: tbs\_Viwango

TBS CENTRAL ZONE Physical Address Kambarage Tower P.O. Box 2956 DODOMA, TANZANIA Tel. No: +255 26 2520310

TBS LAKE ZONE Physical Address NSSF Building, 3<sup>rd</sup> Floor P.O. Box 1814 MWANZA, TANZANIA Tel. No:

TBS NORTHERN ZONE Physical Address NSSF Mafao House Building, 2<sup>nd</sup> Floor P.O. Box 2399 ARUSHA, TANZANIA Tel. No: +255 28 2501127 +255 27 2520143

TBS SOUTHERN HIGHLANDS ZONE Physical Address NHIF Building, 7<sup>th</sup> Floor P.O. Box 1674 MBEYA, TANZANIA Tel No: +255 25 2502848

TBS SOUTHERN ZONE Physical Address MTUWASA Building P. O. Box 1396 MTWARA, TANZANIÁ Tel. No: +255 23 2334477

TBS WESTERN ZONE TBS WESTERN ZONE Physical Address NSSF Building (Mafao House), 2<sup>nd</sup> Floor P. O. Box 1276 KIGOMA, TANZANIA Tel. No: +255 28 2804023